BURY TECHNOLOGIES

LT 9100

SW: L&T_1-1_6_RC

(Look&Talk BT)

Updated: **30.01.2007 / v.06**

No	Phone	Type	Profile HFP					Profile rSAP			Software version
			BT Connection to the last connected phone after ignition is switched on	Self-connection to the last connected phone after getting in BT connection area	Internal phonebook memory of the device	Phone's REDIAL activation	Dial number with use of Voice Tags (voice tags of internal book)	SMS sending	SMS reception	Phone book entries	
1	Motorola	V500	✓	✓	✓	✓	✓	✗	✗	✗	sw: TRIPLETS_G_0B.08.8F5R
2		V550	✓	✓	✓	✓	✓	✗	✗	✗	sw:R376-G-0E.65.26R
3		V551	✓	✓	✓	✓	✓	✗	✗	✗	sw: 08.17.OFR
4		V600	✓	✓	✓	✓	✓	✗	✗	✗	sw: TRIPLETS_G_0B.09.38R
5		V620	✓	✓	✓	✓	✓	✗	✗	✗	sw:R376-G-0E.65.25R
6		V3 RAZR	✓	✓	✓	✓	✓	✗	✗	✗	sw:R374-G-0E.40.3CR
7		E770v	✓	✓	✓	✓	✓	✗	✗	✗	R25221_U_85.83.E1P
8		V3i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R479_G_08.B4.85R
9		SLVR V270	✓	✓	✓	✓	✓	✗	✗	✗	sw:
10		L6	✓	✓	✓	✓	✓	✗	✗	✗	sw:
11		L7	✓	✓	✓	✓	✓	✗	✗	✗	sw:R4513_G_08.B7.5DR_RB
12		E1	✓	✓	✓	✓	✓	✗	✗	✗	sw:R374-G-0E.40.3CR
13		E1000	✓	✓	✓	✓	✓	✗	✗	✗	
14		E1070	✓	✓	✓	✓	✓	✗	✗	✗	R252211LD_U_85.97.C3P
15		U6	✓	✓	✓	✓	✓	✗	✗	✗	sw:R478_G_08.83.76R_A
16		V635	✓	✓	✓	✓	✓	✗	✗	✗	sw:R474-G-08.48.24R_A
17	Nokia	6103	✓	✓	✓	✓	✓	✓	✓	✓	sw:04.90
18		6131	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.70
19		6280	✓	✓	✓	✓	✓	✓	✓	✓	sw:4.26
20		6288	✓	✓	✓	✓	✓	✓	✓	✓	sw:05.92
21		6233	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.38
22		6234	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.50
23		E70	✓	✓	✓	✓	✓	✗	✗	✗	sw:1.0610.05.07
24		E60	✓	✓	✓	✓	✓	✗	✗	✗	sw: V.0610.02.15
25		E61	✓	✓	✓	✓	✓	✗	✗	✗	V. 3.0633.09.04
26		E50	✓	✓	✓	✓	✓	✓	✓	✓	
27		6310	✓	✓	✓	✓	✓	✗	✗	✗	sw:05.01
28		6310i	✓	✓	✓	✓	✓	✗	✗	✗	sw:5.51
29		9300	✓	✓	✓	✓	✓	✓	✓	✓	sw:05.22(01)
30		9300i	✓	✓	✓	✓	✓	✓	✓	✓	V 05.50(00)
31		6600	✓	✓	✓	✓	✓	✗	✗	✗	sw:3.42.1
32		6680	✓	✓	✓	✓	✓	✗	✗	✗	sw:2.04.15
33		6681	✓	✓	✓	✓	✓	✗	✗	✗	sw:3.10.6
34		N71	✓	✓	✓	✓	✓	✓	✓	✓	sw:2.0613.1.12.1
35		N70	✓	✓	✓	✓	✓	✗	✗	✗	sw:2.0536.0.2
36		N73	✓	✓	✓	✓	✓	✗	✗	✗	sw:2.0628.0.0.1
37		N90	✓	✓	✓	✓	✓	✗	✗	✗	sw:5.0607.7.3
38		N91	✓	✓	✓	✓	✓	✗	✗	✗	sw:1.11.003
39		N93	✓	✓	✓	✓	✓	✓	✓	✓	sw:10.0.025
40		N80	✓	✓	✓	✓	✓	✓	✓	✓	sw: 3.0617.0.6
41		6270	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.69
42		6021	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.83
43		6151	✓	✓	✓	✓	✓	✗	✗	✗	sw:03.51
44		6230	✓	✓	✓	✓	✓	✓	✓	✓	sw:04.40
45		6230i	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.23
46		6810	✓	✓	✓	✓	✓	✓	✓	✓	sw:3.30
47		6820a	✓	✓	✓	✓	✓	✓	✓	✓	sw:4.25
48		6822	✓	✓	✓	✓	✓	✓	✓	✓	sw:
49		3250	✓	✓	✓	✓	✓	✗	✗	✗	V03.24
50		8801	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.94
51		8800	✓	✓	✓	✓	✓	✓	✓	✓	sw:03.60
52		N80	✓	✓	✓	✓	✓	✗	✗	✗	sw:3.0617.0.6
53		7710	✓	✓	✓	✓	✓	✗	✗	✗	sw:03.04.2
54		7380	✓	✓	✓	✓	✓	✗	✗	✗	sw:03.80
55	Siemens	SX1	✓	✓	✓	✓	✓	✗	✗	✗	sw:13
56		S65	✓	✓	✓	✓	✓	✓	✓	✓	sw: 50
57		SK65	✓	✓	✓	✓	✓	✓	✓	✓	sw: 50
58		CX75	✓	✓	✓	✓	✓	✓	✓	✓	sw: 05
59		M75	✓	✓	✓	✓	✓	✓	✓	✓	sw: 12
60		SP65	✓	✓	✓	✓	✓	✓	✓	✓	sw:47
61		EL71	✓	✓	✓	✓	✗	✓	✓	✓	sw:31
62	Samsung	SGH-D500	✓	✓	✓	✓	✓	✗	✗	✗	sw:EG001.08
63		SGH-D520	✓	✓	✓	✓	✓	✗	✗	✗	sw:1.0c
64		SGH-D600	✓	✓	✓	✓	✓	✗	✗	✗	sw:TG001.05
65		SGH-D900	✓	✓	✓	✓	✓	✗	✗	✗	sw:D900E.05
66		SGH-X820	✓	✓	✓	✓	✓	✗	✗	✗	sw:0.3b
67		SGH-P900	✓	✓	✓	✓	✓	✗	✗	✗	sw:AE500.03
68	Sony Ericsson	K750i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R1C004.prgCXC1250035-EU-2-C
69		W600i	✓	✓	✓	✓	✓	✗	✗	✗	
70		W700i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R1CA021.prgCXC1250514_EU_1_CR
71		W800i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R1L002.prgCXC1250092_EU_1_C
72		W810i	✓	✓	✓	✓	✓	✗	✗	✗	R4DB005
73		P990i	✓	✓	✓	✓	✓	✗	✗	✗	CXC162037 R7A001
74		W950i	✓	✓	✓	✓	✓	✗	✗	✗	CXC162037 R9C001
75		K700i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R2L001.prgCXC125821_EU_1_C
76		K800i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R1CE001.prgCXC1250211
77		V800	✓	✓	✓	✓	✓	✗	✗	✗	sw:R1J002.prgCXC125839_EU_1_VA
78		K510i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R4CH003.prgCXC1250231_GENERIC_C0
79		Z520i	✓	✓	✓	✓	✓	✗	✗	✗	sw: R3F015
80		K610i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R1BA022.prgCXC1250536_VODAFONE_DEV_TH
81		K600i	✓	✓	✓	✓	✓	✗	✗	✗	sw:R2AC001. prgCXC 1250076_EU_6_MI

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(12ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✗ not working